QV 73 - Henuttauy, Dyn. XIX

Plan, sections, axonometrics





NOTES	
1	Door jambs mostly reconstructed; portion of original right jamb preserved.
2	Traces in the ceiling of pillars built after chamber B was cut. Originally ceiling was painted black or dark blue; a white wash was applied after the pillars were built, and when they were subsequently destroyed two dark squares remained in the ceiling. Since the original survey, the floor has been cleared and the bases of the pillars were found, with a height of approx. 20 cm.
3	Ceiling damaged in rear half of chamber B; dimensions approximate.

















Drawn 2021 by Walton Chan.